


RT-6558 Professional Tool Cart Assembly Instructions



- B 1. Slide the connective panels (5) into two sides of the bases, and secure them with hex socket screws (10), washers (14), skidproof washers (15), and nuts (13).
 - 2. Follow Step B1 to complete the other side, refer to Figure B2.
 - 3. Secure the joints of these two bases (1) by using hex head cap screws (11), washers (14), skidproof washers (15), and nuts (13).





2 removable adjusters




Hex socket screws (10) should be secured in the red positions.

22ITRTXX4000012101





2. Secure the upper panel (6) and the side panels (9) by using hex head cap screws (11), washers (14), skidproof washers (15), and nuts (13).



- E 1. Tighten the rectangular spacers (19-1) loosely underneath the tool pots (18) by using screws (19-2), refer to Figure E1.
 - 2. Place the tool pots (18) on the tool pot racks (16) and put the rectangular spacers (19-1) inside the fillisters of the tool pot racks (16), and then fully tighten the screws (19-2).

